

General Environmental Incident Summary

Incident: 3312

Notice: 5/8/2014

Occurred: 4/30/2014 1300

DEM Incident No:

No Further Action: ☒

Responsible Party: NCT

County: Burleigh

Twp Rng Sec Qtr: 139 78 29

Lat Long + Method: 46.83621 -100.54280 Interpolation from map

Location Description: I 94 over pass Menoken off ramp I mile north of Hwy 10

Submitted By Info: Todd Ricker

2379 Bus Loop I-94

Mandan ND 58554

Received By Info:

Contact Info:

2379 Bus loop I94

Mandan ND 58554

Affected Medium: 03 - soil

Near. Occupied Bldg: 3000 Feet

Type of Incident: Tank Leak

Release Contained: Yes

Reported to NRC: Unknown

Contaminant: Diesel fuel

Volume of Release: 60 gallons

Duration of Release: 15 minutes

Agriculture Related: No

EPA Extremely

Hazardous Substance: Unknown

Number of Fatalities:

Number of Injuries:

Cause of Incident:

Equipment failure cause truck to hit guard rail and tear tank

Risk Evaluation:

None

Potential Env. Impacts:

contaminated soil was removed

Action Taken/Planned:

Soil was place down to stop flow and absorb. 2 yards of soil was removed and replaced.

Wastes Disposal Location:

Other Agencies Involved:

State Highway Patrol, Local Law Enforcement

Updates

Date: 5/8/2014 **Status:** Correspondence

Author: Roberts, Kris

Notes:

Phone contact 5/8/2014 - 04:21 with company receptionist. Requesting call back from listed contact to determine why the spill was not reported to NDDoH for 8 days.

Call back from company representative at 14:52. Stated that the release was verbally reported by phone to the NDDoH Emergency Phone operator within 1 hour of the accident and that the advice given was carried out immediately. Also stated that the requirement to fill out the online EIR was not given until several days later. This has now been corrected, and the company representative has been informed that any spill such as this must be reported through the online EIR within 24 hours.

Updated Volume: None at the time of this update

Date: 5/8/2014 **Status:** Correspondence

Author: Clary, Shane

Notes:

This spill was reported to the department first via the emergency cell phone. Highway patrol on scene were the first to be contacted; stated that a small area of soil had been impacted. After speaking with the highway patrolman, the company contact was then contacted to discuss the accident. The company contact stated that the spill area was small and that he would have the contaminated soil scraped up and disposed of properly. I then contacted the same company contact two days later after realizing that the incident had not yet been reported. The company contact stated that he would submit an incident report when he was back at his office.

Updated Volume: None at the time of this update

Date: 6/15/2018 **Status:** Inspection

Author: Suess, Bill

Notes:

Visited the site and found no signs of impacts. Remediation has been completed and vegetation looks healthy. No photos taken.

Updated Volume: None at the time of this update